



.done files delete


1. Switch USB keyboard
2. Press together „Strl“ and „alt“



3. Press Control




4. Select Explorer and press execute



5. Press hide

6. Follow the path C:\Dlab1\d-Lab.1-dlab1_XXXXXX\export_imagepc
all x.done Files delete



7. Restart the PC with mainbraker